And the second s	CENTRAL INTELLIGEN	CE AGENCY	
	INFORMATION	REPORT	
COUNTRY Hungar			DATE DISTR. 9 Jul 199
SUBJECT Budaor	s Airfield		NO. OF PAGES 3
			110. 07 TAGES
PLACE			NO. OF ENCLS. 1
ACQUIRED			(LISTED BELOW) (A)
DATE			SUPPLEMENT TO
ACQUIRED			REPORT NO.
DATE OF INFORMA	TION		
THIS DOCUMENT CONTAINS INTO	MATION APPROVING THE PAYORAL AUTORIA	• .	•
	THE MEANING OF TITLE 18, SECTIONS 703		•
AND 784, OF THE U.S. CODE, A LATION OF ITS CONTESTS TO SE	RESERVED. ITS TRANSMISSION OR REVE-	THIS IS UN	EVALUATED INFORMATION
ADD 794, PP THE W.A. EDIES, LATION OF ITS CONTEST TO GO PROBLETTED BY LAY, THE DIP!	PARENTS. 175 TRANSMIRION OR REVE- BERGIFF OF AN UNAUTHORIZE PERSON IS SOCRTION OF THIS FORM IS PROMISETED.	THIS IS UN	EVALUATED INFORMATION
1. Budaors of Budaor hills to hills, about to not earth and deal of ninto the	irfield covers an area approx is is located to the west, but the north and an uneven hilly ut 500 meters to the northwes lying. Their highest point whad no artificial drainage sud, but flying operations wer ground within one day.	imately 2,500 b ldings and rail surface to the t of the field, as about 600 me ystem. In rain e not hampered the wi	y 2,000 meters. The vil road tracks to the south east. the south were somewhat of an obsters. The field was of y weather there was a gr
1. Budaors of Budaor hills to hills, about to no dearth and deal of no into the usually him.	irfield covers an area approx is is located to the west, but the north and an uneven hilly ut 500 meters to the northwest lying. Their highest point whad no artificial drainage sud, but flying operations wer ground within one day.	imately 2,500 b ldings and rail surface to the t of the field, as about 600 me ystem. In rain e not hampered the wi ection.	y 2,000 meters. The vil road tracks to the south east. the were somewhat of an obsters. The field was of y weather there was a graince the water was absorbed was not very strong a
1. Budaors of Budaor hills to hills, about ion to dearth and deal of minto the usually h	irfield covers an area approx s is located to the west, bui the north and an uneven hilly ut 500 meters to the northwes lying. Their highest point w had no artificial drainage s ud, but flying operations wer ground within one day. Lew from a south-easterly directed was completely administer.	imately 2,500 b ldings and rail surface to the t of the field, as about 600 me ystem. In rain e not hampered the wi ection. ed by Hungarian	y 2,000 meters. The vil road tracks to the south east. the somewhat of an obseters. The field was of y weather there was a grand was not very strong a Air Force personnel com
1. Budaors of Budaor hills to hills, about on the usually hills.  2. The airfimanded by were stated of the control of the cont	irfield covers an area approx is is located to the west, but the north and an uneven hilly ut 500 meters to the northwest lying. Their highest point whad no artificial drainage sud, but flying operations wer ground within one day.	imately 2,500 b ldings and rail surface to the t of the field, as about 600 me ystem. In rain e not hampered the wi ection. ed by Hungarian arian or Soviet field was used	y 2,000 meters. The vil road tracks to the south east. the somewhat of an obsters. The field was of y weather there was a graince the water was absord was not very strong a Air Force personnel com Air Force tactical unit

1,000 students studying the above subjects and twenty who were taking the squadron and flight engineering officers course. Curricula for the engine and aircraft mechanics course included mathematics, political doctrine, history, geography, engine and aircraft structure, field repair techniques, carpentry, welding, instruments, electricity, photography, armament, radio aerodynamics, physics, chemistry

-2-

50X1

civilian airlines base and no regular flights were scheduled, the Hungarian Soviet Air Company (Magyar Szovjet Lefi Tarsasac) used the field for transporting Hungarian or foreign dignitaries.

- 4. Civilian engine and aircraft mechanics employed by the Hungarian Air Force disassembled defective aircraft engines and frames for inspection by the engineering section. Regular night shifts were not in effect unless there was urgent work. The military maintenance personnel working in the hangars only accomplished minor repair work and routine inspection of aircraft.

  50X1
- 5. The airfield was guarded by a military guard unit. One guard, armed with a Soviet type 7.62mm rifle was stationed at each gate of the airfield twenty-four hours a day. There were about six gate guards and twelve guards patrolling the respective areas.

  the efficiency of the guards was only fair. Everyone entering or leaving the airfield had to show a pass.
- at the airfield there were only prewar air raid shelters constructed of concrete in the hillside about 500 meters from the field. There were no blast pens for aircraft, no anti-aircraft installations, no searchlights or aircraft detection equipment at the field. There were two fire fighting trucks equipped with 3,000 liter containers with chemical fire extinguishing material liquid, (Habolto-Por). The hangars and shops were equipped with five liter and ten liter chemical fire fighting liquid containers, hanging on walls. The firemen had a three months training course in Budapest before being assigned to the airfield.
- 7. The points hereunder refer to sketch, Enclosure (A):

## Point

- #1...... Village of Budaors, population about 4,000. There are no industrial installations in this village.
- #2..... Barbed wire fence which surrounds part of the airfield and three compounds belonging to the airfield. The wire is about two meters high, and supported by concrete posts, spaced at four meter intervals.
- #3..... Grass covered landing area.
- #4...... Gravel-covered road about three meters wide which leads to the western end of the airfield.
- #5..... Hangar used as storage place for old YAK-9 aircraft (without engines). The second floor is used for officers of the engineering section. This building is brick construction with four, reinforced concrete beams. On the southern side of the building there is a double, corrugated iron door, the same size as the side of the hangar. It is about 40 meters long and about 20 meters high. The building is light yellow. The second story has six windows on both of the long sides and three windows on the other two sides. The hangar section has three large windows on the long side and two windows on the other sides.
- #6...... Guards quarters, single story, constructed of brick. It has a gabled, red tile roof, about ten meters long, four meters wide and five meters high. The color of the building is dark yellow.
- #7..... Iron gate, about two meters high and three meters wide.
- #8..... Budapest-Balaton Lake Highway.
- #9..... Apron and taxi strip constructed of concrete blocks. The taxi strip is 130 meters long and four meters wide. The apron is about 20 meters square.
- #10..... Single story hangar, about 30 meters long, 15 meters wide and six meters high. It is constructed of bricks with four, reinforced contrete supports. The northern side has a corrugated, double door of dark green. The building is yellow.
- #10A.... Hangar constructed like the one described in point #10.
- #11..... Iron gate about two meters high, six meters wide and used by vehicles and pedestrians.
- #12..... Single story, brick building used for storage of mechanics' tools. It is about six meters long, four meters wide and four meters high. It has a gabled red tile roof. The color of the building is yellow.

SECRET

€5

50X1


	•
#13	Office building, housing the Operations Section, Secret Service and the headquarters of the Hungarian Air Force Chief Engineer, Lt Col Kalman Horvate. The building is three stories high, constructed of brick and reinforced by concrete supports. The roof is flat, covered with gray slate, and is supported by reinforced concrete transversal
	beams. The control tower is round, five meters in diameter and projects about ten meters above the roof. The roof of the control tower is flat and covered with gray slate. The building is 40 and 20 meters
	long, 20 meters wide and 25 meters high.
#14	Three story brick building, about 20 meters long, nine meters wide and 20 meters high. The first and third floors are used as quarters for enlisted men; the second floor houses the squadron and flight engineer-
	ing officers' school.
<i>#</i> 15	Granite road to Budapest, about five meters wide.
#16	Double track, European, standard-gauge railroad, Budapest-Vienna.
#17	Three story, brick building, about 30 meters long, 20 meters wide and
	20 meters high. It has a gabled, red tile roof.
#18	Building, constructed like the one described in Point #17. It is used
-	as a recreation center for airfield personnel. Classrooms for the
,	engine and aircraft mechanics are located on the two upper floors.
#19	Iron gate, two meters high and six meters wide, used by vehicles and
	pedestrians.
#20	One story guard house, constructed of brick, about ten meters long,
	four meters wide and five meters high. It has a gabled, red tile roof.
#21	Three story, brick building, 30 meters long, 12 meters wide and 25
	meters high, used as quarters for the students at the airfield training center. It has a gabled, red tile roof.
#22	Building, used as quarters for students, constructed like the building
,,	described in Point #21. It also houses the medical dispensary.
#23	Building, used as quarters for students, same construction as the
,, ,	buildings described in Points #21 and #22.
#24	Double track streetcar line from Budapest to Torokealint.
#25	Bus stop.
#26 & 27.	Iron gates, two meters high and six meters wide.

-end-

ENCLOSURE (A): A sketch of Budaors Airfield Area.

A SKETCH OF BUDAORS AIRFIELD AREA

50X1



SECRET

SECRET